Smoke and Dye Testing Summary

High Level Sewershed

Run Summa	ry ———	_					
Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-087	Smoke	9/11/2008	ADS/TM	S11KK1013MH	Dry	Yes	615.13



Smoke and Dye Testing Summary

High Level Sewershed

Run Summa	ary 						
Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-087	Smoke	9/11/2008	ADS/TM	S11KK1013MH	Dry	Yes	615.13

Isolated Pipes —					
	Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
	S11KK1013G1	S11KK1013MH	S13II1042MH	180.6831	8
	S13KK1029G1	S13KK1029MH	S13II1042MH	213.9612	8
	S13KK1008G1	S13KK1008MH	S11KK1013MH	174.4872	8
	S11KK1034G1	S11KK1034DE	S11KK1013MH	45.99807	6

Observations & Photos

No smoke was observed during this test.